



The Stained Leaded Glass Company Ltd

Riverside Studio, 14 Riverside, Waters Meeting Road, Bolton , BL1 8TU

Email: info@stainedleadedglass.co.uk Telephone No: 01204 392777

Limited Company Reg. No. 8441174

VAT Reg. No. 176210620

Quotation

Restoration of Organ Chamber Window with traditional stained glass panel.

Date : 21/1/2026

Rev. Nick Andrews rev.nick@andrewes.org

St. Thomas Church, Werneth, Oldham (OL8 1SF)

Organ Chamber Window with traditional stained glass panel.

Description of Damage

Large lancet stained leaded glass panel size approx. 600mm x 4000mm

Inspection has identified a significant hole affecting stained glass panel.

A section of the leaded panel has failed and has come out of the panel.

The damage is consistent with storm force winds.

Proposed Remedial Work

On-Site Visit 1

- Erect 8 meter scaffolding tower to provide safe access to the window.
- Remove the wire mesh guard
- Remove the damaged stained glass panel from the stone surround and securely board the opening with OSB plywood. Seal to the stone.
- Refit the wire mesh guard

Studio Restoration

- Carefully dismantle the stained glass panel.
- Replace all broken glass pieces.
- Relead and fully restore the panel to its original condition.

On-Site Visit 2

- Erect scaffolding tower for safe access.
- Remove the wire mesh guard
- Reinstall the restored stained glass panel and fit.
- Refit the wire mesh guard

Total Cost: £6,795 + VAT

Cost Breakdown for CIS

Onsite Labour Cost: £ 795 plus vat

Scaffolding tower: £ 500 plus vat

Off site labour and materials cost: £ 5500 plus vat

Unique Tax Reference Number: 687/32157/16725/A



Quotation by: Mr Andrew Seddon, Managing Director. The Stained Leaded Glass Company Limited